

**UNCLASSIFIED**

**AD 414380**

**DEFENSE DOCUMENTATION CENTER**

**FOR**


**SCIENTIFIC AND TECHNICAL INFORMATION**

**CAMERON STATION, ALEXANDRIA, VIRGINIA**



**UNCLASSIFIED**

# DISCLAIMER NOTICE



THIS DOCUMENT IS BEST QUALITY AVAILABLE. THE COPY FURNISHED TO DTIC CONTAINED A SIGNIFICANT NUMBER OF PAGES WHICH DO NOT REPRODUCE LEGIBLY.

**NOTICE:** When government or other drawings, specifications or other data are used for any purpose other than in connection with a definitely related government procurement operation, the U. S. Government thereby incurs no responsibility, nor any obligation whatsoever; and the fact that the Government may have formulated, furnished, or in any way supplied the said drawings, specifications, or other data is not to be regarded by implication or otherwise as in any manner licensing the holder or any other person or corporation, or conveying any rights or permission to manufacture, use or sell any patented invention that may in any way be related thereto.

63-4-5

CATALOGED BY DDC

414380

AS AD No.

**BOEING**

NUMBER, D2-10889-1 Vol. 53


UNCLASSIFIED TITLE ACCEPTANCE SUMMARY REPORT

FLIGHT TEST MISSILE M436 MODEL SPEC. S-133-1007C

MODEL NO WS 133 A CONTRACT NO APO4(647)-289

SERIAL NO — ISSUED TO —

414380



SEATTLE. WASHINGTON

# THE BOEING COMPANY

2-5142

NUMBER D2-10889-1 Vol. 53

UNCLASSIFIED TITLE ACCEPTANCE SUMMARY REPORT

FLIGHT TEST MISSILE M436 MODEL SPEC. S-133-1007C

MODEL NO WS 133 A CONTRACT NO APOL (S47)-289

ISSUE NO — ISSUED TO —

CLASSIFIED TITLE NONE  
(STATE CLASSIFICATION)

CHARGE NUMBER

## SPECIAL LIMITATIONS ON ASTIA DISTRIBUTION

ASTIA may distribute this report to requesting agencies subject to their security agreement approved Fields of Interest and the following

- ☐ UNLIMITED—To all agencies of the Department of Defense and their contractors
- ☐ LIMITED—To U S Military organizations only

This report may be distributed to nonmilitary agencies not approved above subject to Boeing approval of each request.

NOTE The LIMITED category may be checked only because of actual or potential patent, proprietary, ethical or similar implications

DOCUMENT TITLE PAGE U3 4287 9000 REV. 10/61

PREPARED BY Engel J. Luby 7-31-68

SUPERVISED BY Henry Thuhel 7/31/68

APPROVED BY Henry Thuhel 7/31/68

CLASS & DIST N/R  
APPROVED BY —

RELIABILITY N/R  
APPROVAL —

(DATE)

VOL	53	NO.	D2-10889-1
PAGE	0	PAGE 1 OF 1	

# ACTIVE CHANGED PAGE

ACTIVE			CHANGED				ACTIVE			CHANGED					
SECTION	PAGE	DATE	SECTION	PAGE			DATE	SECTION	PAGE	DATE	SECTION	PAGE			DATE
				REVISED	ADDED	DELETED						REVISED	ADDED	DELETED	
O	A														
O	B														
O	C														
O	D														
I	1														
II	1-4														
III	1														
III	-A 1-10														
III	-B 1-14														
IV	-A 1-16														
IV	-B 1-9														
IV	-C 1-4														
V	1-3														
VII	-A 1-3														
VII	-B 1-3														
VII	1														
X	0-54														

REVISED \_\_\_\_\_

US 4200 1000

**BOEING**

VOL 53

NO D2-10889 -1

SE 0

PAGE B

## CORRELATION INDEX

61-30 PARA.	TBC CORRELATION DATA PAGE	TERMINOLOGY
6.4 (A)	Section I	Introduction
6.4 (A K)	Section II	Certification Forms
6.4 (A)	Section II 2a	Approved Specification Changes Notices to 3-139-1007C
6.4 (B)	Section II 4	Condition of Acceptance
6.4 (A)	Section III	Equipment Identification
6.4 (A)	Section III-A	Instrumentation Configuration Log
6.4 (P)	Section III-B	Engineering Drawing Index
6.4 (H & M)	Section IV-A	M&IR Index
6.4 (A)	Section IV-B	Actual Configuration
6.4 (A)	Section IV-C	Committed Changes
6.4 (D&H)	Section V	Functional Test Complete
	Section VI	(Deleted)
6.4 (I)	Section VII-A	Contract Specification Non-Conformance Report (Functional)
6.4 (G)	Section VII-B	Equipment Failures
6.4 (CAF)	Section VIII	Shortages
	Section IX	(Deleted)
6.4 (I)	Section X	Engineering Deviations and Waivers

## CONTENTS

REFERENCE: Operating Procedure 234-021 Dated 5 Feb. 1962.

### INDEX

SECTION I	INTRODUCTION
SECTION II	CERTIFICATION FORMS
SECTION II 2a	APPROVED SPECIFICATION CHANGE NOTICES TO S-133-10070
SECTION III	EQUIPMENT IDENTIFICATION
SECTION III-A	INSTRUMENTATION CONFIGURATION LOG
SECTION III-B	ENGINEERING DRAWING INDEX
SECTION IV-A	M & IR INDEX
SECTION IV-B	ACTUAL CONFIGURATION
SECTION IV-C	COMMITTED CHANGES
SECTION V	FUNCTIONAL TEST COMPLETE
SECTION VI	(DELETED)
SECTION VII-A	CONTRACT SPECIFICATION NON-COMFORMANCE ITEMS (FUNCTIONAL)
SECTION VII-B	EQUIPMENT FAILURES
SECTION VIII	SHORTAGES
SECTION IX	(DELETED)
SECTION X	ENGINEERING DEVIATIONS AND WAIVERS



## SECTION

### ● INTRODUCTION

#### 1. SCOPE

- a. This data identifies and describes the actual status of End Items, designated for First Article Customer Inspection or Team Acceptance review (Reference: AFFSD Exhibits 61-51 & 61-30). It includes any Waivers or Deviations that exist or are required for Non-Conformance Items. Status reporting will be at the delivery level unless otherwise noted.
- b. Responsibility of maintenance to include Base Commitments is transferred to the Base Quality Control Planning Unit receiving the equipment.

#### 2. PURPOSE

- a. To establish a composite status for use by Base personnel to determine status of equipment received.
- b. To serve as a record of First Article End Item Acceptance as required by RSD-STL and AFQC at Seattle for delivery to Base Installations.

SECTION II

CERTIFICATION OF EQUIPMENT COMPLETION

The undersigned, being Chairman of the AFBSD, WS133A Acceptance Team, certifies the following:

1. The equipment described below is complete to the extent indicated on the transfer or Shipping Authorization Form and its addenda.
2. The equipment is suitable for shipment to the location described below, under the jurisdiction of the Boeing Company for future test and/or work as required to satisfy the contract specified below.

Equipment Model No. 21-50122-36 Equipment Serial No. M436

Equipment Nomenclature R&D SUB-SYSTEM ASSEMBLY

Destination BATC Contract Affected AF04(647)-289

T/S Authorization Voucher No. EUI2160 EUI2161 EUI2162 EUI2163

2d Lt. Ronald J. Canella  
AFBSD Acceptance Team Chairman

SECTION II

THE BOEING COMPANY AND SPACE TECHNOLOGY LABORATORIES


TECHNICAL CERTIFICATION

EQUIPMENT MODEL NO. 21-50122-36 S/N 11436

NOMENCLATURE R & D SUB-SYSTEM ASSEMBLY

The undersigned has reviewed the Engineering Data on the subject equipment and certifies the following:

1. The equipment is technically adequate to perform its intended function.
2. The equipment meets all the specifications and requirements of Model Specification S-133-1007C Instrumentation Sub-System-Airborne R&D WS-133A, dated DEC. 9, 1961 1961, including the approved SCN's listed on page 2a, with the exception of the Waivers and Deviations pages 1 through 5A in D2-10489, Volume 53, Section X, Acceptance Summary Report.

  
7/31/63  
ENGINEERING REPRESENTATIVE  
FOR THE BOEING COMPANY

NOT REPRESENTED  
REPRESENTATIVE FOR SPACE  
TECHNOLOGY LABORATORIES

REVISED \_\_\_\_\_

US 4200 7000 (WAS PAC 41310)

BOEING | VOL 53 | NO D2-10489-1  
| SEC 11 | PAGE 2 | →

# SECTION II

## APPROVED SPECIFICATION CHANGE NOTICES TO S-133-1007c

### APPROVED SCN's

3	238-239
5-12	241-244
14-19	249-250
28-31	254
34-35	260-264
37-40	270
42-44	275
46-47	277
49-51	278
52-54	282
58-59	
63	
66-67	
69	
70	
71-80	
85-87	
90-91	
93-95	
110-118	
120	
128-131	
139-146	
163-165	
168-170	
189-193	
215	
216-225	
229-231	
233-235	

REVISED \_\_\_\_\_

U.S. 4200 2000 (WAS R-11310)

**AIR FORCE QUALITY CONTROL CERTIFICATION OF EQUIPMENT READY  
FOR ACCEPTANCE TEST**

**EQUIPMENT  
PART NO.**

21-50122-36

**SERIAL NO.**

M436

**NOMENCLATURE**

R&D SUB-SYSTEM ASSEMBLY

The undersigned has reviewed the equipment and its associated records:

**1. VISUAL AND PHYSICAL INSPECTION OF EQUIPMENT**

- |   |                                      |                          |
|---|--------------------------------------|--------------------------|
| A. Finish Satisfactory  | Yes <input checked="" type="radio"/> | No <input type="radio"/> |
| B. Workmanship Satisfactory   | Yes <input checked="" type="radio"/> | No <input type="radio"/> |
| C. Freedom from Damage  | Yes <input checked="" type="radio"/> | No <input type="radio"/> |
| D. Installation Complete Except as Noted on Contractor's Shortage and/or Incomplete List. | Yes <input checked="" type="radio"/> | No <input type="radio"/> |
| E. Authorization for Shortage or Incompletes Noted in Item "D" has been received.         | Yes <input checked="" type="radio"/> | No <input type="radio"/> |

**2. SPECIFICATION AND DRAWING STATUS**

- |   |                                      |                          |
|---|--------------------------------------|--------------------------|
| A. All Applicable Specs have been complied with Except as Noted on Contractor's Request for Waiver or Deviation List. | Yes <input checked="" type="radio"/> | No <input type="radio"/> |
| B. All Documents and Specs have been Approved by AF/BSD, or Waivers obtained.   | Yes <input checked="" type="radio"/> | No <input type="radio"/> |
| 3. BAC Acceptance Tags (BAC Form U)-4001-5000 have been properly Validated and Affixed to the Equipment.              | Yes <input checked="" type="radio"/> | No <input type="radio"/> |
| 4. All Test Equipment Utilized in Conducting Acceptance Tests were properly Calibrated.                               | Yes <input checked="" type="radio"/> | No <input type="radio"/> |

SIGNATURE

*Joe S. Peha 7/31/63*

SIGNATURE

*L. Marchesini 7/31/63*

NAME (Print)

JOE S. PEHA

NAME (Print)

L. Marchesini

Boeing Company  
Quality Control Representative  
Seattle, Washington

Air Force Quality Control  
Air Force Plant Representatives Office  
Boeing Company  
Seattle, Washington

REVISED \_\_\_\_\_

US 4200 2000 (FAS PAT 41101)

**BOEING**

VOL 53

NO D2-10889 -1

SEC. II

PAGE 3

Conditions of Acceptance

Comments

SECTION III

EQUIPMENT IDENTIFICATION FORM

DATE 7-31-63

~~GTN~~ ~~or~~ FTM SERIAL NO. M436

MODEL or EQUIPMENT SPECIFICATION S-133-1007C

TOP DRAWING 21-50120

PART NUMBER 21-50120-36

NOMENCLATURE R&D SUB-SYSTEM ASSEMBLY

# INSTRUMENTATION CONFIGURATION LOG

INSTRUMENTATION CONFIGURATION LOG

MISSILE 436									
SECTION NO. 43									
NO.	MEAS. CODE	NOMENCLATURE	NAME OF MFG.	EQUIPMENT SERIAL NO. (BAC/ATG)	PART NUMBER	WIRE EQUIP ITEM NO.	INSTL. DATE	MR. IR USED ON.	
1		Power Splitter & Filter	Sigma	010734/61	LPT-12B	A91	11-28-2	25-17869-38	
2		Event Marker	Electro	020456/335	10-20401-1	R4 (A60)	10-31-2	25-33994-37	
3		Event Marker	Electro	021144/503	10-20401-1	R2 (A60)	10-31-2	25-33994-37	
4		Event Marker	Electro	021145/504	10-20401-1	R1 (A60)	10-31-2	25-33994-37	
5		Event Marker	Electro	021167/505	10-20401-1	R3 (A60)	10-31-2	25-33994-37	
6		RF Unit	U. Electro Dyn.	021210/553	10-20402-40	A83	11-28-2	25-17866-37	
7		Multiplexer Prog. Box	Radiation	0046RT	10-20402-41	A22	10-28-2	21-50035-4	
8		Multiplexer Box	Radiation	0067RP/0009	10-20402-42	A26	11-2-2	21-50035-14	
9		R.F. Package	United Electro Dynamics	040800/619	10-20403-7	A80	12-6-2	25-17867-37	
10		V.C.O. Package	United Electro Dynamics	040865/600	10-20403-8	A80	12-18-2	25-17867-37	
11		Triplexer	Allen Bradley	020804/1099	10-20409	A82	11-21-2	25-15718-999	
12		Voltage Regulator	Electro Dev.	021446/74	10-20410	VR1	11-21-2	25-15718-999	

REVISED

UN 4788 2000

BOEING

VOL 53

NO

02-10889-1

SEC 111-A

1



INSTRUMENTATION CONFIGURATION LOG

MISSILE 436 SECTION NO. 43									
NO.	MEAS. CODE	NOMENCLATURE	NAME OF MFG.	EQUIPMENT SERIAL NO. (BAC/ATG)	PART NUMBER	WIRE EQUIP ITEM NO.	INSTL. DATE	WIR USED ON.	
13		Switch	Kinetics	020451/0000146	10-20420-7	S5	11-9-2	25-33595-59	
14		Transfer Switch	Kinetics	021790/0134	10-20420-8	S2	11-14-2	25-33595-59	
15		Switch	Kinetics	800919/0143	10-20420-9	S6	11-9-2	25-33595-59	
16		Receiving Set	Motorola	021398/122	10-20428-2	A9	11-28-2	25-17869-38	
17		Receiving Set	Motorola	021397/121	10-20428-2	A5	11-28-2	25-17869-38	
18		Linear Accelerometer	Statham	020380/11857	10-20454-5	MT84	10-5-2	25-21584-7	
19		Linear Accelerometer	Statham	020381/11861	10-20454-5	MT83	10-1-2	25-21584-8	
20		Linear Accelerometer	Statham	04068/11271	10-20454-6	MT82	10-5-2	25-21584-4	
21		D.C. Amplifier	Electro Dev.	016320/159	10-20459-2	A29	12-6-2	25-17867-37	
22		Staging Switch	Electro Dev.	020778/186	10-20476	S1	11-14-2	25-33596-26	
23		Thermocouple Ref. Junction	Servo	021429/129	10-20478-11	MR6	11-7-2	25-22282-16	
24		Transformer	United Electro Dyn.	582	10-20833-26	A146	10-16-2	25-17062-35	

## INSTRUMENTATION CONFIGURATION LOG

MISSILE 436									
SECTION NO. 43									
MEAS. NO.	MEAS. CODE	NOMENCLATURE	NAME OF MFG.	EQUIPMENT SERIAL NO. (BAC/ATG)	PART NUMBER	WIRE EQUIP ITEM NO.	INSTL. DATE	MR IR USED ON.	
25		Transformer	United Electro Dynamics	594	10-20833-26	A147	10-16-2	25-17062-35	
26		Multiplexer Prog.	Boeing	0002	21-50035-4	A22	11-28-2	25-17866-37	
27		Multiplexer	Boeing	0008/442	21-50035-37	A26	4-24-3	25-17866-37	
28		Command Destruct Antenna	Boeing	M414 E2-1	25-15837-5	E 6	11-27-2	25-15718-959	
29		Command Destruct Antenna	Boeing	M411-2	25-15837-5	E 7	11-27-2	25-15718-959	
30		Command Destruct Antenna	Boeing	M413-2	25-15837-5	E 8	11-27-2	25-15718-959	
31		Telemetry Antenna	Boeing	M431-1	25-15850-9	E 1	12-5-2	25-15718-959	
32		Telemetry Antenna	Boeing	M429-3	25-15850-9	E 2	12-5-2	25-15718-959	
33		Telemetry Antenna	Boeing	M430-1	25-15850-9	E 3	7-29-3	25-15718-959	
34		Mistram Antenna	Boeing	A32-1	25-25518-14	E 9	3-29-3	25-15718-959	
35		Mistram Antenna	Boeing	M431-2	25-25518-14	E 10	3-29-3	25-15718-959	
36		FSMR Monitor	Boeing	M446	25-25843-13	A 153	5-21-3	25-15718-959	

# INSTRUMENTATION CONFIGURATION LOG

MISSILE 436									
SECTION NO. 43									
LINE NO.	DESCRIPTION	NAME OF MFG.	EQUIPMENT SERIAL NO. (EAC/ATG)	PART NUMBER	WIRE EQUIP. ITEM NO.	INSTL. DATE	MRIR USED ON.		
37	Waveguide Assy.	Technicraft	82152	25-27648-1	W2	1-4-3	25-15718-959		
38	Waveguide Assy.	Technicraft	800975/1793T	25-27648-15	W3	5-21-3	25-15718-959		
39	Waveguide Assy.	Technicraft	800420/5882Y	25-27648-13	W1	5-21-3	25-25493-7		
40	Waveguide Assy.	Technicraft	800856/3964Z	25-27648-14	W3	5-21-3	25-25493-7		
41	Mistram Transponder	Boeing	174-4112	25-28056-2	See line 42 & 43		25-25493-7		
42	Transponder	GFE	21	7641450GIMODA	A151	7-22-63	25-28056-2		
43	Filter	GFE	30	7641481G1	A152	7-22-63	25-28056-2		
44	Filter	Genistron	502	25-28059-1	A181	12-5-2	25-15718-959		
45	Matching Unit	Boeing	M436	25-34555-7	A51	11-13-2	25-33594-37		
46	Power Splitter	Boeing	M436	29-13515	A85	10-2-2	25-15187-9009		
47	Capacitor Assy.	Boeing	M436	29-21662-1	A187	11-15-2	25-33596-26		

REVISED

US 4288 0000

BOEING

VOR 53

NO 111-A

NO 111-A

02-10889-1



# INSTRUMENTATION CONFIGURATION LOG

MISSILE 436									
SECTION NO. 45									
MEAS. NO.	DESCRIPTION	NAME OF MFG.	EQUIPMENT SERIAL NO. (BAC/ATG)	PART NUMBER	WIRE EQUIP. ITEM NO.	INSTL. DATE	WTR USED ON.		
1	A0058 Bridge Strain Gage	Baldwin	Z01235	BAC S-44A-1	MT 176	7-19-2	25-28538-912		
2	A5058 Bridge Strain Gage	Baldwin	Z01236	BAC S-44A-1	MT 180	7-19-2	25-28538-912		
3	A0068 Bridge Strain Gage	Baldwin	Z01237	BAC S-44A-1	MT 177	7-19-2	25-28538-912		
4	A5068 Bridge Strain Gage	Baldwin	Z01238	BAC S-44A-1	MT 181	7-19-2	25-28538-912		
5	A0078 Bridge Strain Gage	Baldwin	Z01239	BAC S-44A-1	MT 178	7-19-2	25-28538-912		
6	A5078 Bridge Strain Gage	Baldwin	Z01240	BAC S-44A-1	MT 182	7-19-2	25-28538-912		
7	A0088 Bridge Strain Gage	Baldwin	Z01241	BAC S-44A-1	MT 179	7-19-2	25-28538-912		
8	A5088 Bridge Strain Gage	Baldwin	Z01242	BAC 44A-1	MT 183	7-19-2	25-28538-912		
9	A0978 Calorimeter	RyCal	040881 6875	G-11104-B-30-002-870	MT 486	12-19-2	25-28586-12		
10	Control Box	Radiation	02158R	10-20402-47	A121	10-28-2	21-50035-5		
11	Auxiliary Box	Radiation	03298R	10-20402-48	A7	10-28-2	21-50035-15		
12	Auxiliary Box	Radiation	03308R	10-20402-48	A119	10-23-2	21-50035-16		

REVISED

119 4288 8000

ROEING

VOL

33

33

D2-10889

1



# INSTRUMENTATION CONFIGURATION LOG

MISSILE 436									
SECTION NO. 45									
MEAS. NO. CODE	NOVENOMIATURE	NAME OF MFG.	EQUIPMENT SERIAL NO. (BAC/ATG)	PART NUMBER	WIRE EQUIP. ITEM NO.	INSTL. DATE	MR. IR. USED ON.		
13 A144T	Thermocouple	Aero Res.	020638/781	10-20477-9120	MT 640	10-26-2	25-28538-912		
14 A263T	Thermocouple	Aero Res.	020627/780	10-20477-9120	MT 13	10-26-2	25-28538-912		
15 A259T	Thermocouple	Aero Res.	020632/785	10-20477-9120	MT 12	10-26-2	25-28538-912		
16 —	Thermocouple Ref. Jet.	Servo Mech.	021789/138	10-20478-11	HR 5	11-20-2	25-31976-26		
17	Control Box	Boeing	0002 (M436)	21-50035-5	A121	11-13-2	21-50122-9017		
18	Aux. Box	Boeing	0002 (M436)	21-50035-15	A7	11-13-2	21-50122-9017		
19	Aux. Box	Boeing	0002 (M436)	21-50035-16	A119	11-13-2	21-50122-9017		
20	Bridge Comp. Network	Boeing	M430 11 of 19	25-25223-902(-5)	A92	1-2-3	21-50122-9017		
21	Bridge Comp. Network	Boeing	M430 6 of 19	25-25223-902(-5)	A93	1-2-3	21-50122-9017		
22	Bridge Comp. Network	Boeing	M431-13	25-25223-902(-5)	A98	1-2-3	21-50122-9017		
23	Bridge Comp. Network	Boeing	A31-5	25-25223-903(-6)	A94	1-2-3	21-50122-9017		
24	Bridge Comp. Network	Boeing	M432-2	25-25223-903(-6)	A95	1-2-3	21-50122-9017		

BOEING

VEN

53

NO

D2-10889

1

MISSILE 436  
SECTION NO. 45

[illegible]

REVISÉ D

19 4200 2000

## RIDEING

1. 2

53

NO 72-17889-1

2

# INSTRUMENTATION CONFIGURATION LOG

MISSILE 436 SECTION NO. 47							
MEAS. NO.	DESCRIPTION	NAME OF VEG.	EQUIPMENT SERIAL NO. (EAC/ATG)	PART NUMBER	WIRE EQUIP ITEM NO.	INSTL. DATE	MR. TR USED ON.
1	AC98H Callorimeter	Ry-Cal	040892/6889	0-1104-B-30-002-070	MT757	12-26-2	25-28586-12
2	Control Box	Radiation	0102RR	10-20402-47	A118	10-28-2	21-50035-6
3	Auxiliary Box	Radiation	0333RW	10-20402-48	A4	10-23-2	21-50035-17
4	Auxiliary Box	Radiation	0139RW	10-20402-48	A116	10-23-2	21-50035-18
5	D.C. Amplifier	Electro Dev. Corp.	019629/78	10-20459-2	A217	11-15-2	21-50122-9018
6	Thermocouple	Aero Res.	020634/787	10-20477-9120	A159T	10-15-2	25-28539-914
7	Thermocouple	Aero Res.	020643/796	10-20477-9120	A331T	10-15-2	25-28539-914
8	Thermocouple Ref. Unit	Servo-Mech.	022106/143	10-20478-11	HR 2	2-7-63	25-31976-25
9	Control Box	Boeing	0002(436)	21-50035-6	A118	11-28-2	21-50122-9018
10	Auxiliary Box	Boeing	0002(436)	21-50035-17	A4	11-28-2	21-50122-9018
11	Auxiliary Box	Boeing	0002(436)	21-50035-18	A116	11-28-2	21-50122-9018
12	Matching Unit	Boeing	0435	25-34554-8	A88	2-11-3	21-50122-9018

REVISED

US 4288 9000

BOEING

53

NO D2-10889-1

1-1-A

1-1

02

SECTION NO. 47

[illegible]

REVISIT

U.S. 2200 200.0

## ROEING

1. 2. 3.

53

NO

02-10882-1

9



• ۱۹ ۴۲۸۸ ۹۸۸۸

-1

## SECTION III-B

## ENGINEERING DRAWING INDEX

MISSILE SECTION 43 (M436)

Indenture

1 2 3 4 5 6

PART NUMBER

21-50122-36  
     25-15718-46  
         25-20600-46  
             25-16196-6  
             25-15850-9  
             25-16197-4  
                 25-15837-5  
                     29-13522  
                     29-13542  
             25-19562-6  
             25-27080-3  
                 25-27048-2  
                 25-27060-1  
                     26-11826-1  
                     26-11830-1  
                 26-11835-1  
                 26-11836-1  
                 26-11852-1  
                 26-11853-1  
                 29-20499-4  
                 29-20500-4  
                 25-26852-64  
                 25-26852-62  
                 25-26852-63  
             25-15187-223  
             25-16465-20  
                 26-10260-3  
             29-21032-5  
             29-19463-3  
             26-8362-2  
             29-19464-6  
             29-19462-4  
             29-20839-1  
             29-17515  
             22-19461-1  
             25-23297-11  
                 29-18417-5  
                 26-10794-1  
                 26-10795-1  
                 26-10794-4  
                 29-18417-8  
             26-9358  
             26-9450  
             26-9463

NOMENCLATURE

R&D Sub System Assy. AMR-FTM  
 R&D Section Assy.  
 Compartment Assy.  
 Ant. Instl.-Tele. Sec. 43  
 Ant. Tele.-Assy. of  
 Ant. Instl.-C.D. Sec. 43  
 Ant. C.D. Assy. of  
 Support Bracket Assy.  
 Antenna-Command Destruct Assy. of  
 Marking Instl.  
 Duct. Instl.  
 Channel-Assy. of  
 Duct-FM Tray Cooling-Assy. of  
 Clamp-Assy. of  
 Hat Sec.-Assy. of  
 Clamp-Assy. of  
 Clamp-Assy. of  
 Filler-Assy. of  
 Filler-Assy. of  
 Clamp-Assy. of  
 Clamp-Assy. of  
 Duct-Assy. of  
 Filler-Assy. of  
 Filler-Assy. of  
 Instr. Sec. Assy.  
 Struct. Instl. Peripheral Equip. Supt.  
 Base Plate Assy. of  
 Tray-Assy. of  
 Tray-Assy. of  
 Support Brkt. P.C.M. Tray Assy. of  
 Tray-Assy. of  
 Wire Tray-Assy. of  
 Tray-Assy. of  
 Power Splitter  
 Aft Wire Tray Assy. of  
 Channel-Equip-Support Assy. of  
 Bracket-Assy. of  
 Angle-Assy. of  
 Support Angle-Assy. of  
 Angle-Assy. of  
 Bracket-Assy. of  
 Tray Assy. of  
 Bracket-Wire Tray Support Fwd. Assy. of  
 Tray Support PCM Tray Assy. of

REVISED

43 4000 2000 1948 040 010101

REVISION

VOL 53

NO D2-10009-1

SEC III-B

PAGE 1

SECTION IIL-B  
ENGINEERING DRAWING INDEX

MISSILE SECTION 43 (M436)

Indenture  
1 2 3 4 5 6

PART NUMBER

NOMENCLATURE

29-16439-1	Bracket-Wire Bundle Support Assy. of
29-15355	Support Fitting PCM Tray Assy. of
29-15617	Fitting Accelerometer Support L.H. Assy. of
29-15619	Fitting Accelerometer Support R.H. Assy. of
26-8365-4	Fitting Assy. of
29-16577-1	Tube-Assy. of
29-15595-4	Bracket Assy. of
29-14031-7	Fitting-Assy. of
29-14031-16	Fitting-Assy. of
29-14031-20	Fitting-Assy. of
29-14031-25	Fitting-Assy. of
29-14031-17	Fitting-Assy. of
29-13452-11	Fitting-Attach; C.D. Tray-Assy. of
29-13452-12	Fitting-Attach, C.D. Tray-Assy. of
29-13450-7	Fitting-Attach Telemetry Tray, Assy. of
29-13450-8	Fitting-Attach Telemetry Tray, Assy. of
29-20486-1	Bracket Assy.
29-20569-1	Bracket Assy.
26-11859-1	Support Assy.
26-11863-1	Support Assy.
25-20538-7	Insulation Inst.
25-20537-18	Plug Instl.
26-12135-1	Plate Bearing Assy. of
25-28834-35	Wire & Equipment Instl.
25-21800-55	Coaxial Cable Bundle Tele. Assy. of
25-21800-56	Coaxial Cable Bundle Tele. Assy. of
25-21800-57	Coaxial Cable Bundle Tele. Assy. of
25-21800-25	Coaxial Cable Bundle Tele. Assy. of
25-21800-44	Coaxial Cable Bundle Tele. Assy. of
25-21800-46	Coaxial Cable Bundle Tele. Assy. of
25-21800-47	Coaxial Cable Bundle Tele. Assy. of
25-21800-48	Coaxial Cable Bundle Tele. Assy. of
25-21800-49	Coaxial Cable Bundle Tele. Assy. of
25-21800-53	Coaxial Cable Bundle Tele. Assy. of
25-21800-24	Coaxial Cable Bundle Tele. Assy. of
25-21584-4	Accel. Bundle-Assy. of
10-20454-6	Linear-Accelerometer (-3 Opt.)
25-21584-7	Accel. Bundle-Assy. of
10-20454-5	Linear-Accelerometer
25-21584-8	Accel. Bundle-Assy. of
10-20454-5	Linear-Accelerometer

SECTION III-B  
ENGINEERING DRAWING INDEX

MISSILE SECTION 43 (M436)

1 2 3 4 5 6

PART NUMBER

NOMENCLATURE

25-28059-1	Filter - Assembly of
25-22282-16	Cable - Assembly of
10-20478-11	Ref. Junction Assembly
25-33595-88	Wire Bundle Comp. Assembly of
10-20420-7	Switch - Assembly of
10-20420-9	Switch - Assembly of
10-20483-4	Protective Cover Connector
10-20483-1	Connector - Umbilical
10-20410	Voltage Regulator
10-20409	Triplexer
25-33195-85	Electric Bundle
29-24153-11	Shield - Cover Wire Bundle Assembly of
29-24153-1	Shield Base Wire Bundle Assembly of
29-21390-1	Tray - Assembly of
29-21390-2	Cover - Assembly of
29-23567-1	Hat Section - Assembly of
25-25496-7	Waveguide and Antenna Installation
25-25843-13	WAVEGUIDE DUMMY MONITOR, ASSY OF
29-20757-1	Clamp Support Antenna Assembly of
25-25518-14	Antenna
25-27648-1	Waveguide Assembly of
25-27648-13	Waveguide Assembly of
25-27648-14	Waveguide Assembly of
26-11971-1	Clamp Assembly
29-20784-1	Clamp Assembly
29-20784-2	Clamp Assembly
29-20784-3	Clamp Assembly
25-27648-15	Waveguide Assembly of
25-16400-14	Tray Installation - FM/FM
25-17867-37	Tray Assembly - FM
25-33596-42	Wire Bundle Assembly
29-21662-1	Capacitor - Assembly of
10-20476	Switch Staging
10-20420-8	Switch Transfer and Test
25-16406-52	Tray Structure - Assembly Calibrate
29-15166-4	Fitting - Assembly of
29-15183-4	Fitting - Assembly of
29-16466-1	Clamp - Assembly of
10-20403-8	VCO Package
10-20403-7	R. F. Package
10-20459-2	Amplifier D. C. Signal A29
29-15475-16	Base - Assembly of
29-15475-18	Cover - Assembly of
25-16402-7	Tray Assembly Command Destruct
25-17869-38	Tray Assembly C. D.
25-16408-27	C. D. Tray - Assembly of

REVISED

U.S. GOVERNMENT PRINTING OFFICE: 1964

**ENGINEERING**

VOL. 53

NO D2-10889 -1

SEC. III-B

PAGE 3

## SECTION III-B

## ENGINEERING DRAWING INDEX

MISSILE SECTION 43 (M436)

1 2 3 4 5 6

PART NUMBERNOMENCLATURE

29-15293-2	Fitting - Assembly of
29-15290-1	Fitting - Assembly of
29-15925	Splice Box - Assembly of
25-17062-25	Bundle Assembly
25-17062-26	Bundle Assembly
25-17062-35	Bundle Assembly
10-20833-26	C. D. Insulation Transformer
10-20428-2	Receiving Set C. Range Safety
LPF-12B	Low Pass Filter
29-15925-1	Cover Assembly
29-15494-7	Cable Support - Assembly of
29-15494-8	Cable Support - Assembly of
29-16792-1	Box - Assembly of
26-9969-1	Cover - Assembly of
25-29817-1	Duct Installation MISTRAM Tray Section 43
29-22596-1	Duct - FM Cooling MISTRAM Tray Assembly of
26-11730-1	Retained Screw Assembly
25-12935-1	Flexible Tube Assembly
29-22556-1	Angle - Support Cooling Air Duct, FM Assembly of
29-22556-2	Angle - Support Cooling Air Duct, FM Assembly of
25-16401-12	Tray Installation - Tracking Beacon
25-25493-7	Tray Assembly Mistran
25-25494-1	Tray Structure Assembly
26-11912-2	Back - Storage MISTRAM Waveguide Assembly of
29-20330-1	Fitting R. H. Tray Attach., Assembly of
29-20331-1	Fitting L. H. Tray Attach., Assembly of
29-20381-1	Guide - MISTRAM Tray Assembly of
29-20756-2	Wire Support - Tray MISTRAM, Assembly of
25-25495-1	Elect. Cable Bundle MISTRAM Tray Assembly of
25-25495-2	Elect. Cable Bundle Mistran Tray Assembly of
29-20756-1	Wire Support Tray Assembly
25-28056-2	Receiver - Transmitter Transponder & Filter
25-16199-16	Tray Installation PCM/FM
25-17866-37	Tray Assembly PCM
25-16143-122	PCM Tray Structure
29-14046-2	Fitting - Assembly of
29-14047-2	Fitting - Assembly of
25-27040-1	Duct - Assembly of
25-26852-10	Duct - Assembly of (Opt. to 25-27040-1)
29-20417-1	Duct - Assembly of
25-26852-7	Duct - Assembly of (Opt. to 29-20417-1)
10-20402-40	RF Unit (A83)

REVISED

40 0000 0000 (1000 000 01010)

ENGINEERING

VOL 53

NO D2-10889 -1

SEC III-B

PAGE 4

## SECTION III-B

## ENGINEERING DRAWING INDEX

Indenture

MISSILE SECTION 43 (M436)

1 2 3 4 5 6

PART NUMBERNOMENCLATURE

29-15585	Base Assy. of
29-15586	Support Base Assy. of
29-15616	Support Clamp-Assy. of
29-16095	Cover-Support Assy. of
29-16097	Liner Instl. PCM Tray
29-15585-10	Cover Assy. of
29-15584-16	Cover Assy. of
29-15585-16	Cover Assy. of
25-33594-59	Elect. Cable Bundle PCM Assy. of
25-34555-7	Matching Unit Modular Assy. of
29-14185-4	Box Assy. of
29-26811-1	Clamp Support Assy. of
29-26838-1	Clamp Assy. of
29-26846-1	Terminal Board Assy. of
25-34002-1	Module-Assy. of
25-34054-1	Module-20V Pwr. Mon. Assy. of
25-34055-1	Module-Dest. V. Divider Assy. of
25-34556-1	Module-Calorimeter Cal. Assy. of
25-34019-1	Module-Battery Divider Assy. of
29-25258-1	Module Trigger Network Assy. of
25-16462-8	Event Marker-Instr. Assy. of
10-20401-1	Event Marker
29-15345-13	Support Assy. of (Opt. to -6)
29-15345-6	Support Assy. of
25-33185-91	Elect. Bundle Patch Plug Assy. of (P160)
25-33185-82	Elect. Bundle Patch Plug Assy. of (P161)
25-33185-82	Elect. Bundle Patch Plug Assy. of (P162)
25-33185-111	Elect. Bundle Patch Plug Assy. of (P163)
25-33185-109	Elect. Bundle Patch Plug Assy. of (P164)
25-33185-96	Elect. Bundle Patch Plug Assy. of (P159)
21-50035-1	PCM/FM Telemetry Components (Opt.)
21-50037-1	PCM/FM Telemetry Components (Opt.)
21-50038-1	PCM/FM Telemetry Components (Opt.)
21-50039-1	PCM/FM Telemetry Components (Opt.)
21-50040-1	PCM/FM Telemetry Components (Opt.)
21-50041-1	PCM/FM Telemetry Components (Opt.)
21-50042-1	PCM/FM Telemetry Components (Opt.)
21-50036-1	PCM/FM Telemetry Components
21-50036-4	Multiplexer-Programmer Assy. of
10-20402-41	Multiplexer-Programmer Box
10-20402-53	DC to DC Converter, Sync.
10-20402-73	12V Voltage Regulator #1
21-50036-37	Multiplexer, Assy. of
21-50036-7	Multiplexer, Sub-Assy.
10-20402-42	Multiplexer Box
10-20402-79	50MV Amplifier & Clamp Assy.

REVISED

US ARMY DDD FORM 1040 11-61

ENGINEERING	VOL. 53	WD 2-10689-1
SEC. III-B	PAGE	5

# SECTION III-B

## ENGINEERING DRAWING INDEX

MISSILE SECTION 43 (M436)

### Indenture

1 2 3 4 5 6

### PART NUMBER

25-15799-24  
25-15799-25  
29-15639  
25-15773-23  
29-17982-2  
25-19501-9  
25-25173-7  
25-25173-8  
25-25172-4  
25-25236-1  
25-25236-2  
25-25236-3  
25-25174-13  
29-13708-1  
29-13717  
26-8372  
29-19218-1  
29-19285-4  
10-20439-7  
10-20439-8

10-20402-80  
10-20402-81

### NOMENCLATURE

5V Amplifier & Clamp Assy.  
10MV Amplifier & Clamp  
Opt. & Interchangeable With 25-15799-25  
Command Destruct Battery  
Wire Bundle Assy. of  
Case-Batt., Assy. of  
Captive Fastener-Assy. of  
Electrolyte Kit  
Opt. & Interchangeable with 25-25173-8  
Battery Tray-Instr. Sec., Assy. of  
Cover Assy. of  
Electric Cable Bundle Assy. of  
Jumper Assy. of  
Jumper Assy. of  
Case-Batt. Tray Assy. of  
Brkt. Fl. Support Battery Tray Assy. of  
Fitting Assy. of  
Retainer Assy. of  
Support Flange Battery Tray Assy. of  
Resistor Package Assy. of  
Cartridge Assy.  
Cooling Valve

# SECTION III-B

## ENGINEERING DRAWING INDEX

MISSILE SECTION 45 (M436)

Indenture  
1 2 3 4 5 6

### PART NUMBER

21-50122-36  
25-23207-34  
25-29156-2  
25-26626-4  
25-25864-17  
25-20599-42  
25-20599-27  
25-23208-139  
25-23117-4  
25-24153-58  
25-25619-8  
25-24153-59  
25-25619-2  
25-24154-25  
25-24154-26  
25-24154-27  
25-24155-1  
25-25441-2  
25-25441-7  
25-25467-17  
25-25467-18  
25-25467-25  
25-25511-27  
25-25511-28  
25-25511-19  
25-25511-20  
25-25511-21  
25-25511-22  
25-25511-25  
25-24621-6  
26-11748-3  
26-11749-1  
29-13483  
29-19633-5  
29-20128-3  
29-20165-1  
29-20845-1  
29-21393-1  
29-21394-1  
25-31659-7  
25-32416-1  
25-32417-1  
25-32418-1  
25-32751-1  
25-32751-2

### NOMENCLATURE

R&D Sub-System AMR-FTM  
Interstage Assy. Insulated  
Marking Installation  
Bracket Installation G&C Support  
Bracket Assy. of  
Wire Tray Instl. Interstage 2&3  
Wire Tray Assy. of  
Interstage Assy., Interstage 2-3  
Splice Assy. of  
Adapter Ring Assy. of  
Shield Assy.  
Adapter Ring Assy. of  
Shield Assy.  
Separation Ring Assy.  
Separation Ring Assy. of  
Separation Ring Assy.  
Fitting Assy. of, Detonator  
Splice Fitting, Assy. of  
Splice Fitting, Assy. of  
Door Assy. of, Ordnance Access  
Door Assy. of, Ordnance Access  
Door Assy. of, Ordnance Access  
Fitting Assy. of, Opt. to -19  
Fitting Assy. of, Opt. to -20  
Fitting Assy. of  
Fitting Assy. of  
Fitting Assy. of  
Fitting Assy. of  
Fitting Assy. of  
Ordnance Fitting Assy.  
Door-Ordnance Fitting  
Door-Ordnance Fitting  
Adaptor Ring Aft.  
Bracket Assy. of, Lanyard  
Doubler-Door Ordnance Access Assy.  
Door-Access Skirt Removal Booster Assy.  
Ordnance Fitting Fwd. Assy.  
Doubler Assy. of, Raceway  
Door Assy. of, Ordnance Access  
Rack Installation Accelerometer  
Fitting Assy. of  
Fitting L.H. Support Accelerometer Assy. of  
Fitting R.H. Support Accelerometer Assy. of  
Fitting Main Beam Accelerometer Assy. of  
Fitting Main Beam Accelerometer Assy. of



## SECTION III-B

## ENGINEERING DRAWING INDEX

Indenture

MISSILE SECTION 45 (M436)

1 2 3 4 5 6

PART NUMBERNOMENCLATURE

26-13946-1	Tube-Accelerometer Rack Assy. of
26-13946-2	Tube-Accelerometer Rack Assy. of
29-25287-1	Bracket Support Wire Bundle Assy. of
29-25287-2	Bracket Support Wire Bundle Assy. of
29-24359-1	Tube Fitting Accelerometer Rack, Assy. of
29-24433-1	Channel Support Accelerometer Assy. of
29-24447-1	Support Receptacle Assy. of
29-25217-1	Bracket Wire Support Assy. of
29-25314-1	Clamp Wire Bundle Support Assy. of
29-24447-5	Support Receptacle Assy. of
29-24996-1	Support Receptacle Assy. of
29-25314-2	Clamp Wire Bundle Support Assy. of
25-28538-78	Wire Support & Instrumentation Instl. Insul.
25-35868-2	Strain Gage Instl. Insulated
25-35887-1	Wire Installation Interstage Strain Gage
29-24709-1	Support-Matching Unit Sec. 45 Assy. of
25-28586-12	Calorimeter Assy. of
C1104-B-30-002-070	Calorimeter
10-20477-9120	Thermocouple Assy.
25-37738-1	Ablation Gage Instl.
25-35899-7	Ablation Gage
25-35669-41	Cork Insulation Instl. External
25-18180-10	Equip. Rack Instl.
29-16264-1	Brkt. Assy. of
29-16982-1	Brkt. Assy. of
25-18178-7	Supt. Beam-Assy. of
29-18662-1	Beam Supt.-Assy. of
29-18662-2	Opp. 29-18662-1
29-18692-1	Wire Supt.-Assy. of
25-18141-44	Instrumentation Equipment Installation
21-50035-2	PCM/FM Telemetry Components (Opt.)
21-50037-2	PCM/FM Telemetry Components (Opt.)
21-50038-2	PCM/FM Telemetry Components (Opt.)
21-50039-2	PCM/FM Telemetry Components (Opt.)
21-50040-2	PCM/FM Telemetry Components (Opt.)
21-50041-2	PCM/FM Telemetry Components (Opt.)
21-50042-2	PCM/FM Telemetry Components (Opt.)
21-50036-2	PCM/FM Telemetry Components
21-50036-5	Control Box, Assy. of
10-20402-47	Control Box
110-20402-53	DC to DC Converter Syne.
10-20402-74	12V Voltage Reg. #2
10-20402-84	10MV Amplifier & Clamp Assy.
10-20402-85	50MV Amplifier & Clamp Assy.
10-20402-86	5V Amplifier & Clamp Assy.
21-50036-15	Auxiliary Box, Assy. of
21-50036-8	Auxiliary Box, Sub Assy.
10-20402-48	Auxiliary Box

REVISED

US GPO: 1965 O-615101

ENGINEERING

VOL 53

MOD 2-10889 -1

SEC III-B

PAGE 8

## SECTION III-B

## ENGINEERING DRAWING INDEX

## Indenture

MISSILE SECTION 45 (M436)

1 2 3 4 5 6

PART NUMBERNOMENCLATURE

21-50036-16  
 21-50036-9  
 10-20402-48  
 25-34553-7  
 29-14180-4  
 29-26898-1  
 29-26907-1  
 25-34002-1  
 25-34054-1  
 25-34556-1  
 25-34599-1  
 29-25262-1  
 25-25223-5  
 25-25223-6  
 25-31976-26  
 10-20478-11  
 25-36618-11  
 25-19931-12  
 25-19947-58  
 25-19949-6  
 25-36152-32  
 25-36846-29  
 25-19900-242  
 25-19900-258  
 25-19900-244  
 25-19900-249  
 25-19900-246  
 25-19900-253

Auxiliary Box, Assy. of  
 Auxiliary Box, Sub. Assy.  
 Auxiliary Box  
 Matching Unit  
 Box, Assy. of  
 Clamp, Assy. of  
 Clamp Supt. Assy. of  
 Module-Ref. Voltage Assy. of  
 Module-20V Pwr. Monitor Assy. of  
 Module, Calorimeter Cal. I Assy. of  
 Module, Calorimeter Cal. II Assy. of  
 Ablation Gage Assy. of (Module)  
 Bridge Completion Network  
 Bridge Completion Network  
 Thermocouple Ref. Unit Assy. of (HR 5)  
 Thermocouple Junction Box  
 Elec. Cable Instl. R&D Sub. Assy.  
 Elec. Cable Bundle Aft. Removable Panel  
 Elec. Cable Bundle Rowy. 3rd Stg. Eng.  
 Bundle Assy. ECB Instr. Sec. 45 & 47  
 Bundle Assy. Sec. 45 Rack  
 Marking Instl.  
 Patch Plug (P152)  
 Patch Plug (P153)  
 Patch Plug (P154)  
 Patch Plug (P155)  
 Patch Plug (P156)  
 Patch Plug (P180)

REVISED

US ARMY 5000 1740 SAC 01101

DOEING

VOL 53

MOD2-10889 -1

SEC III-B

PAGE 9

## SECTION III-B

## ENGINEERING DRAWING INDEX

## Indenture

1 2 3 4 5 6

PART NUMBER

21-50122-36  
 25-31011-19  
     25-23236-806  
         29-21546-4  
         29-21368-1  
         29-21368-2  
         25-26693-1  
         29-20169-1  
         29-16843-1  
         29-16843-2  
         29-16843-5  
         29-16844-1  
         29-18853-1  
         29-19410-1  
         29-19428-6  
         25-26051-1  
         25-24140-2  
         25-25188-5  
         26-13780-1  
         25-24140-12  
         29-23773-1  
         26-14020-1  
         29-16843-10  
         26-14189-1  
         26-14189-3  
         29-19611-12  
         29-26873-1  
         25-33890-23  
         25-26831-6  
         29-25787-1  
         29-25788-800  
         25-24139-43  
             29-24427-4  
         25-24139-49  
         25-29593-4  
         25-30160-3  
 25-28539-50  
     29-25529-1  
     10-20477-9120  
     25-28586-12  
         C1104-B-30-002-070  
     29-21042-1  
     25-37738-1  
         25-35899-1  
 25-26627-8  
     25-25864-5  
     25-25864-11

MISSILE SECTION 47 (M436)NOMENCLATURE

R&D Sub-System Assy. AMR-FTM  
 Interstage Assy. Insulated  
 Interstage Assy.  
 Shield-Explosive Assy.  
 Fitting, Panel Tie, Assy. of  
 Fitting, Panel Tie, Assy. of  
 Fwd. Ordnance Housing, Assy. of  
 Door Ordnance Access, Assy. of  
 Doubler, Assy. of  
 Doubler, Assy. of  
 Doubler, Assy. of  
 Door-Ordnance Access, Assy. of  
 Detonator Housing Aft., Assy. of  
 Shield-Explosive, Assy. of  
 Doubler-Detonator, Assy. of  
 Fitting-Detonator, Assy. of  
 Fitting, Assy. of (-15 Opt.)  
 Splice Plate, Assy. of  
 Bracket Support, Assy. of  
 Fitting, Assy. of (-14 Opt.)  
 Back-up Angle, Assy. of  
 Back-up Angle, Assy. of  
 Doubler, Assy. of  
 Clip-Retainer-Assy. of  
 Clip-Retainer, Assy. of  
 Bracket-Lanyard, Assy. of  
 Splice Plate Assy. of  
 Seat Plate Assy. of  
 Tube, Assy. of  
 Aft.-Ordnance Housing, Assy. of  
 Retainer, Assy. of  
 Adaptor Ring Assy. of Upper (-48 Opt.)  
 Ring Seal Supt. Assy. of  
 Adaptor Ring Assy. of Lower  
 Wire Severance Instl. Deadface  
 Wire Severance Instl. Deadface  
 Wire Supt. & Instr. Instl.  
 Cover Instr. Protective Assy. of  
 Thermocouple  
 Calorimeter Assy.  
 Calorimeter  
 Support Assy. of  
 Ablation Cage Instl.  
 Ablation Cage  
 Bracket Instl. G&C Support  
 Support Bracket, Assy. of  
 Support Clamp Assy. of

REVISED \_\_\_\_\_

US GPO: 1969 O-348-048 (11/1/69)

DESIGN | VOL 53 | NO D2-10689 -1  
 SEC III-B | PAGE 10

## SECTION III-B

## ENGINEERING DRAWING INDEX

Indented

MISSILE SECTION 47 (M436)

1 2 3 4 5 6

PART NUMBERNOMENCLATURE

25-25864-29	Bracket Support, Assy. of
29-24426-3	Clamp Brkt. G&C Cable, Assy. of
25-35633-7	Cork Insulation Instl.
25-29156-6	Marking Instl.
25-17233-55	Support Rack Instl. Instr.
26-9271-3	Bracket, Assy. of
26-9272-3	Bracket, Assy. of
26-16435-1	Bracket, Assy. of
29-18599-7	Tray Assy.
25-37013-1	Cork Insul. Instl. External Instg. 1-2
25-18140-44	Instr. Equip. Installation
21-50035-3	PCM/FM Telemetry Components (Opt.)
21-50037-3	PCM/FM Telemetry Components (Opt.)
21-50038-3	PCM/FM Telemetry Components (Opt.)
21-50039-3	PCM/FM Telemetry Components (Opt.)
21-50040-3	PCM/FM Telemetry Components (Opt.)
21-50036-3	PCM/FM Telemetry Components
21-50036-6	Control Box Assy. of
10-20402-47	Control Box
10-20402-53	DC to DC Converter, Sync.
10-20402-74	12V Voltage Regulator #2
21-50036-18	Auxiliary Box Assy. of
21-50036-12	Auxiliary Box Sub-Assy.
10-20402-48	Auxiliary Box
21-50036-17	Auxiliary Box Assy. of
21-50036-11	Auxiliary Box, Sub-Assy.
10-20402-48	Auxiliary Box
25-34554-8	Matching Unit, Modular, Instg. Assy. of
29-25262-1	Module-Ablation Gage Assy. of
29-14192-4	Box Assy. of
25-34002-1	Module-Voltage Ref. Assy. of
25-34054-1	Module-20V Power Mon. Assy. of
25-34556-1	Module Cal. Calib. I, Assy. of
29-26898-1	Clamp Assy. of
29-26907-1	Clamp Supt. Assy. of
10-20459-2	D.C. Amplifier
25-31976-25	Thermocouple Ref. Unit Assy. of
10-20478-11	Thermocouple Junction Box
25-36617-11	Cable Instl.-Elect. R&D Sub-Assy.
25-19949-8	Elect. Cable Instl. Sec. 45 & 47, 49
25-34535-27	Wire Instl. R&D Fwd. Adaptor Ring
25-20290-1	Insulation Instl.
25-19935-58	Bundle Assy.
25-20290-1	Insulation Instl.
25-36846-26	Marking Instl.
25-19900-237	Patch Plug P145 Assy. of
25-19900-256	Patch Plug P146 Assy. of

REVISED \_\_\_\_\_

VS 4200 2000 READ ONE 411101

~~SECRET~~

VOL 53

WD 02-10889-1

SEC III-B

PAGE 11



# SECTION III-B

## ENGINEERING DRAWING INDEX

Indenture

MISSILE SECTION 47 (M436)

1 2 3 4 5 6

### PART NUMBER

25-19900-261  
25-19900-240  
25-19900-241  
29-19900-247  
25-36153-32  
25-19946-72  
  
25-36179-4  
29-27165-1

### NOMENCLATURE

Patch Plug P147 Assy. of  
Patch Plug P148 Assy. of  
Patch Plug P149 Assy. of  
Patch Plug P178 Assy. of  
Elect. Cable Bundle-Instr. Rack Assy. of  
Elect. Cable Bundle-Raceway 2nd Stage  
Engine, Assy. of  
Insul. Instl. R&D Wiring Stage III  
Clamp-Hook Type Assy. of

# SECTION III-B

## ENGINEERING DRAWING INDEX

MISSILE SECTION 49 (M436)

Indenture

1 2 3 4 5 6  
PART NUMBER

NOMENCLATURE

21-50122-36  
25-33938-91  
25-29156-5  
25-35582-12  
25-36472-1  
25-23196-7  
29-28030-1  
29-27752-1  
10-20477-9120  
25-37738-2  
25-35899-8  
25-33898-800  
25-36616-11  
25-20290-1  
25-36846-25  
25-19928-12  
25-19945-53  
25-36180-8

R&D Sub-System Assy.  
Skirt Assy.-Insulated  
Marking Instl.  
Wire & Instrumentation Instl.  
Support Instl., Wire Routing  
Calorimeter Assy.  
Bracket Assy.  
Support Assy.  
Thermocouple  
Ablation Gage Instl.  
Ablation Gage  
Skirt Assy.  
Elec. Cable Instl. R&D Sub-Assy.  
Insulation Installation  
Marking Instl.  
Elect. Cable Bundle, Raceway  
Elect. Cable Bundle, Raceway  
Insulation Instl. R&D Wiring Stage I

SECTION III-B  
ENGINEERING DRAWING INDEX

MISSILE SECTION Multi (M436)

Indenture

1 2 3 4 5 6  
PART NUMBER

21-50122-36  
25-35487

29-22327-3

10-20987-13  
10-20987-12

NOMENCLATURE

R&D Sub-System Assy. AMR-FTM  
Tech. Sheet Guided Msl. R&D Sub Syst. Assy.

Switch Timer Premature Separation (CTLI)

Timer Interval  
Timer Interval

## SECTION IV-C

## COMMITTED ENGINEERING CHANGES

CHANGE	STATUS	REMARKS	DDRC STATUS		COMP/INC
			LAST PG.	DATED	
<u>CCP</u>					
646	Inc	Comp. for Seattle Resp.	32	12-12-62	Comp.
728-2	Comp.	In Seq. M436	2	6-29-62	Comp.
805	Inc.	Comp. for Seattle Resp.	22	4-8-63	Comp.
836	Inc.	Complete for Seattle Resp.	30	12-5-62	Comp.
886	Comp.		5	3-26-63	Comp.
1049	Comp.		22	6-25-63	Comp.
1128	Comp.		1	4-5-63	Comp.
1158	Comp.		7	7-12-63	Inc.
<u>PBR</u>					
4145	Comp.		2	8-2-62	Comp.
4147	Comp.		1	6-19-62	Comp.
4189	Comp.		1	8-9-62	Comp.
4198	Comp.		2	9-7-62	Comp.
4202	Comp.	In Seq. M436	2	8-15-62	Comp.
4232	Comp.		1	10-26-62	Comp.
4247	Comp.		1	11-12-62	Comp.
4254	Comp.		5	11-21-62	Comp.
4258	Comp.		1	11-7-62	Comp.
4259	Inc.	Comp. for Seattle Resp.	1	12-6-62	Comp.
4267	Comp.		1	12-5-62	Comp.
4270	Comp.		6	2-26-63	Comp.
4272	Comp.		1	12-26-62	Comp.
4275	Comp.		6	1-24-63	Comp.
4279	Comp.		3	1-18-63	Comp.



## SECTION IV-C

## COMMITTED ENGINEERING CHANGES

CHANGE	STATUS	REMARKS	LAST PO.	DDRC STATUS DATED	COMP/INC
<del>FRB</del> 4280	Comp.		1	1-29-63	Comp.
4290	COMP		6	4-23-63	Comp.
8557-181	Comp.		1	8-8-62	Comp.
8587-198	Comp.		1	12-7-62	Comp.
<del>8595-233</del>	<del>COMP</del>		<del>4</del>	<del>7-26-63</del>	<del>COMP</del>
80700-186	Comp.		1	9-18-62	Comp.
80700-190	Comp.		1	10-19-62	Comp.
80700-191	Comp.		1	10-19-62	Comp.
80700-193	Comp.		1	11-2-62	Comp.
80700-194	Comp.		1	11-19-62	Comp.
80700-195	Comp.		1	11-19-62	Comp.
80700-196	Comp.	In Seq. 436	1	11-27-62	Comp.
80700-197	Comp.		1	12-17-62	Comp.
80700-199	Comp.		1	12-17-62	Comp.
80700-202	Comp.	In Seq. 436	1	1-3-63	Comp.
80700-210	Comp.		1	2-28-63	Comp.
80701-186	Comp.		1	9-19-62	Comp.
80701-191	Comp.	In Seq. 436	1	10-18-62	Comp.
80701-193	Comp.		1	11-19-62	Comp.
80701-198	Comp.		1	12-17-62	Comp.
80701-199	Comp.		1	12-14-62	Comp.
80701-210	Comp.		1	2-28-63	Comp.
80702-196	Comp.	In Seq. 436	1	11-27-62	Comp.
80702-198	Comp.		1	12-20-62	Comp.

REVISED

NO 4280 2000 (FAS 045 61010)

BEING | VOL 53 | NO D2-10889 -1  
| SEC IV-C | PAGE 2

## SECTION IV-0

## COMMITTED ENGINEERING CHANGES

CHANGE	STATUS	REMARKS	LAST PG.	DDRO STATUS DATED	COMP/INC
80702-199	Comp.		1	12-14-62	Comp.
80702-205	Comp.		1	1-21-63	Comp.
80702-208	Comp.		1	12-15-62	Comp.
80702-210	Comp.		1	2-28-63	Comp.
80703-205	Comp.		1	1-21-63	Comp.
80710-192	Comp.	In Seq. 436	1	10-31-62	Comp.
80811R-1	Comp.		1	7-11-62	Comp.
80953	Comp.		1	10-23-62	Comp.
80956	Comp.		1	11-8-62	Comp.
80957	Comp.		1	11-14-62	Comp.
80961	Comp.		1	12-29-62	Comp.
80968	Comp.		1	1-24-63	Comp.
80969	Comp.		1	2-26-63	Comp.
80970	Comp.		1	2-28-63	Comp.
83504	Comp.		1	8-24-62	Comp.
83518	Comp.		2	9-18-62	Comp.
83546	Inc.	Comp. for Seattle Resp.	1	10-3-62	Comp.
83566	Comp.		1	10-24-62	Comp.
83582	Comp.		1	10-31-62	Comp.
83601S	Comp.		1	12-7-62	Comp.
83674	Inc.	Comp. for Seattle Resp.	1	3-11-63	Comp.
83610-1	Inc.	Comp. for Seattle Resp.	8	3-13-63	Comp.
85009-193	Comp.		1	11-9-62	Comp.
800037R1	Comp.		1	12-6-62	Comp.

# SECTION IV-C

## COMMITTED ENGINEERING CHANGES

CHANGE	STATUS	REMARKS	DDRC STATUS		
			LAST PO.	DATED	COMP/INC
800037R-2	Comp.		1	12-21-62	Comp.
83732	COMP.		1	6-11-63	Comp.
83755	INC.	COMPLETE FOR SEATTLE RESP.	1	6-6-63	Comp.

7-31-63  
*[Signature]*  
 Test Engineering  
 Acknowledgement of  
 Configuration Status

REVISED \_\_\_\_\_  
 00 0000 0000 (FAS 000 01010)

**BOEING** | VOL 53 | NO D2-10809 ->  
 | SEC IV-C | PAGES 4

## SECTION VII-A

## CONTRACT SPECIFICATION NON-CONFORMANCE ITEMS (OPERATIONAL)

MISSILE SECTION M 436 Multi Section

WIR PART NUMBER	JOB NUMBER	SERIAL NUMBER
21-50122-93436 UER U078331 DISCREPANCY:	57317	M436

Reference: D2-7969, Volume 36, Section 7 and UER 078327, Job No. 57317

The following channels were out of tolerance as read out on NIXIE during Channel Verification Run #2

CHANNEL	% P. S. Error	REQUIREMENT
BO 63E	-1.6%	+ 1.2%
BO 49X	-1.32%	+ 1.2%
BO 50X	-1.60%	+ 1.2%

Fix:

See D2-10889-1, Volume 53, Section X, Page 4 for waivers.

21-50122-93436 UER U078230	57318	M436
-------------------------------	-------	------

DISCREPANCY:

Reference: D2-7969, Volume 36, Section 8.

IO 34E reads 41% on stripout and should be 37.5%. Model specification requires + 3% tolerance.

Fix: See D2-10889-1, Volume 53, Section X, Page 5 for waivers

21-50122-93436 UER U 078277 DISCREPANCY:	57318	M436
--	-------	------

Reference D2-7969, Volume 36, Section 8, Run #2 and Computer Run 441 dated 7-24-63.

The following channels were out of tolerance during the running of the above test: 0037E, 0092E, A064T, I006E, R015A

Fix: See D2-10889-1, Volume 53, Section X page <sup>4</sup> for waivers.

21-50122-93436 UER U170203 DISCREPANCY:	57317	M436
---	-------	------

The following channels were out of tolerance during channel verification Run #3 reference computer dump test No. 500: 0037E, 0092E, A064T, A007S, R015A

Fix: See D2-10889-1, Vol. 53, Section X, Page 4 for waivers.

REVISED \_\_\_\_\_

U3 4200 2000 (WAS SAC 413101)

DOING	VOL 53	NO D2-10889 -1
	SEC VII-A	PAGE 1

SECTION VII-A

CONTRACT SPECIFICATION NON-CONFORMANCE ITEMS (OPERATIONAL)

MISSILE SECTION M 436 Multi Section

PAIR PART NUMBER

JOB NUMBER

SERIAL NUMBER

21-50122-93436

57320

M436

UER U170319

DISCREPANCY:

The following channels were out of tolerance during 45 Section "X" Axis vibration per D2-7969 Volume 36, Section 10. Reference computer dump test No. 450 Run #1: A 007S

FIX: See D2-10889-1, Volume 53, Section X, Page 5 for waivers.

21-50122-93436

57318

M436

UER U078222

DISCREPANCY:

Reference D2-7969, Volume 36, Sections 0 & 8 and UER 078329, J/N 57318

The following channels were out of tolerance during 43 "Y" Axis vibration as read out on oscillograph stripout: B017A, B018A, B050X.

FIX: See D2-10889-1, Volume 53, Section X, Page 5 for waivers.

21-50122-93436

57319

M436

UER U170295 Page 4

DISCREPANCY:

Ref: D2-7969, Vol. 36, Sec. 9 Para. 6.4.8

During 43 "X" Axis the receiver signal strength on PCM oscillograph recording NoX4533 dropped 1.62db. The maximum deviation allowed  $15 \pm 1.5$ db.

FIX: See D2-10889-1, Vol 53, Sec. X, Page 5A For waivers.

21-50122-93436

57319

M436

UER U 164764 Page 5

DISCREPANCY:

Ref: D2-7969, Vol. 36, Sec 9 Run #2

The following listed channels are out of tolerance per computer run #431 on Data taken per the above ref. doc. during 43 "X" Axis vibration run #2.

GO 37E GO92E B015A

FIX: See D2-10889-1, Vol 53, Sec X, Page 5 for waivers

REVISED

US 4766 2000 (FAS SAC 41310)

DOING VOL 53 NO D2-10889-1  
SEC VII-A PAGE 2

# SECTION VII-A

## CONTRACT SPECIFICATION NON-CONFORMANCE ITEMS (OPERATIONAL)

MISSILE SECTION M436 Multi Section

### PAIR PART NUMBER

### JOB NUMBER

### SERIAL NUMBER

21-50122-93436

57319

M436

UER U078228 Page 7

### DISCREPANCY:

Ref: D2-7969, Vol 36, Sec. 9

Channel IO34E output on stripout is 41.0% and voltage measurement gives 37.35%  
Model spec requires  $\pm 3\%$ .

FIX: See D2-10889-1, Vol 53, Sec. X Page 5 For waiver.

21-50122-93436

57319

M436

UER U078221 Page 8

### DISCREPANCY:

Ref: D2-7969, Vol. 36, Sec. 0&9 and UER U078326 Page 6 J/N 57319.

The following channels were out of tolerance during 43 "X" Axis vibration as  
read out on oscillograph strip out:

RO17A RO 18A RO50X

FIX: See D2-10889-1, Vol. 53, Sec X, Page 5 for waivers

21-50122-36

57310

M436

UER U078281

### DISCREPANCY:

Due to removal & Replacement of the 25-15850-9 Telemetry Antenna per UER U170193 &  
U078278 on P/N 21-50122-36(43), S/N 57323. RF Power, per D2-7969 Vol 36 Sec 2  
is no longer valid.

FIX: See D2-10889-1 Vol 53 Sec 10 Page 3 for waivers

REVISED \_\_\_\_\_

U3 4200 2000 (WAS SAC 4131)M

**ENDING**

VOL 53

NO D2-10889-1

SEC VII-A

PAGE 3

## SECTION VII-B

## EQUIPMENT FAILURES

MISSILE SECTION 436 MULTI SEC.

<u>M&amp;R PART NUMBER</u>	<u>JOB NUMBER</u>	<u>SERIAL NUMBER</u>
21-50122-36 (47) UER U165123 (Page 20)	39450	M436

**Discrepancy:**

Reference D2-7969, Vol. 36, Section 3, Electrical Wire Diagram 25-15203, Sheet 19 and UO48698 J/N 57313. During Run #1 of channel verification, Section 3, D2-7969, Vol. 36, the output of transducer A312T was observed to be approximately 10 percent of noise. Investigation on UER 048698 J/N 57313 states that the circuitry of A312T exhibit no capacitance to a bridge across it. The capacitance of A312T Channel 3 of HR2 S/B 22 Micro-Farads per D10-20478.

**Fix**

Removed 25-31976-25, S/N M436 and replaced with S/N M441.

21-50122-93436 U147217 (Page 11)	57317	M436
-------------------------------------	-------	------

**Discrepancy**

Reference D2-7969, Vol. 36, Section 7, Run #1. The following listed channels were out of tolerance per the above Reference Run #1 Computer Dump #500: R015A, R019A, R020A, R021A, G037E, G040E, G075E and G092E.

**Fix**

Removed 21-50035-37 S/N 0009 and replaced with 21-50035-37, S/N0008.

21-50122-93436 UER U170123	57318	M436
-------------------------------	-------	------

**Discrepancy**

Reference D2-7969, Vol. 36, Paragraph 6.1.1, Run #1. During the upswEEP, the downswEEP and both Quiescent Data Runs of M436 "Y" axis vibration, the MISTRAM Transponder lost lock-on on the calibrate channel. The range channel lost lock-on during the downswEEP and Quiescent Data Runs.

**Fix**

Removed Transponder Assembly 25-28056-2, S/N M438R and replaced with 25-28056-2, S/N 0002R. (67 / 4)

REVISED \_\_\_\_\_

US GPO: 1969 O-348-018

DOEING	VOL 53	NO D2-10889-1
	SEC VII-B	PAGE 1

# SECTION VII-B

## EQUIPMENT FAILURES

MISSILE SECTION M 436 (Multi Section)

### M&IR PART NUMBER

### JOB NUMBER

### SERIAL NUMBER

21-50122-93436  
UER U170296 and U178226

57316

M 436

### DISCREPANCY:

Reference: D2-7969, Vol. 36, Section 6, Run #8, paragraph 9.8.13 and on

The following listed phase shift dial readings were observed which results in an "out of tolerance" condition per reference document. 8 M. C. Phase shift should not be more than 4° per paragraph 9.12.

### PARAGRAPH REFERENCE

### DATA

9.8.13	84° 11'
9.9.19	79° 19'
9.9.25	83° 42'
9.10.4	73° 51'
9.9.26	-6° 37'
9.10.5	67° 14'
9.11.4	79° 04'
9.11.5	73° 03'
9.12	7° 57'

Also, during sub-systems tests, Loss of Lock of phase Lock-on was observed frequently, making it difficult to complete sensitivity tests.

### Fix:

Removed Transponder Filter Assembly 25-28056-2, Serial No. 0002R (69 & 4) and replaced with Serial No. 436R (74 and 34).



# SECTION VII-B

## EQUIPMENT FAILURES

### MISSILE SECTION M 436 (Multi Section)

<u>M&amp;IR PART NUMBER</u>	<u>JOB NUMBER</u>	<u>SERIAL NUMBER</u>
21-50122-93436 UER U170293	57316	M 436

REFERENCE: D2-7969, Volume 36, SE 6, Run #9, Para. 8.4.6

#### DISCREPANCY:

When the sweep switch is "ON" and the run advance switch is depressed to obtain illumination of the 264 MC light, the calibrate channel loses lock. Unable to check sensitivity with automatic sweep on.

UER U078286

REFERENCE: D2-7969, Volume 36, Section 6, Run #9, paragraph 8.5.3 and UER'S 170207 and 170293.

#### DISCREPANCY:

The Transponder (Serial No. 74) will not exhibit a phase locked condition for a period of 40 + 10 seconds using manual sweep mode (See U 170293 and U 170294)

FIX: (UER'S U 170293 and U 078286)

Removed Transponder Filter Assembly 25-28056-2, Serial No. M 436R (74 and 34) and installed Serial No. 441R (21 and 30)

SECTION VII

SHORTAGES

SEPARATE SHIPMENT

1. (1) 10-20987-12 and (1) 10-20987-13 Premature Separation Switch Assy.  
They are shipped direct from Electro Developmental Corp. to BATC.
2. (2) 10-20439-7 Cartridge Assy. and (2) 10-20439-8 Cooling Valve.  
They are shipped direct from Tailing Corp. to BATC.
3. (1) 25-19501-9 Electrolyte Kit. The parts are shipped direct from  
Yardney Electric Corp. to BATC.
4. (2) 10-20942-3 C/D Battery Assy. To be shipped direct from Tele-  
Computing Corp. to BATC.
5. 25-25173-8 Battery Tray and 25-15799-25 C/D Battery 43 Section.  
BATC O.D. Dates to be determined by Mfg. Engr.  
25-15799-25 is optional to and interchangeable with 25-15799-24.  
25-25173-8 is optional to and interchangeable with 25-25173-7.

SHIP-SHORT ITEMS

None

7-31-63  
*[Signature]*  
Test Engineering  
Acknowledgement of  
Configuration Status *[Signature]*

ENGINEERING WAIVERS AND DEVIATIONS AND WAIVERS

REVISED \_\_\_\_\_

U3 4200 2000 (WAS BAC 4131D)

<b>BOEING</b>	VOL 53	NO D2-10009-1
SEC X	PAGE 0	→

Date: 7-29-63Missile Effectivity FTM 436

Event Record No.:

Spec. or Doc. No.: D2-3603-3

Revisions:

Date: 12-9-61Spec. or Doc. Title: Model Specification S-133-1007C - Instrumentation  
Subsystem - Airborne - R&D WS-133A, WS-133A-MWaiver X

Deviation \_\_\_\_\_

Page No: 135

Paragraph No: 3.5.1

Paragraph Title: Electro-Interference - Equipment

Description:

I. The PCM/FM RF Section did not meet all the specification requirements of GM 07-59-2617A. A waiver is requested for the following areas of non-compliance:

## A. Antenna Conducted Spurious Emanations - Transmitted Keydown

PCM/FM TR-10 "D" Frequency

<u>Frequency</u>	<u>db "out of spec"</u>
144.5 mc	11
201.0 mc	35
208.0 mc	25
223.0 mc	24.8
345.5 mc	33.1
460.0 mc	29
1.39 kmc	29
1.62 kmc	35.7
1.85 kmc	29
2.075 kmc	11
2.3 kmc	11
2.53 kmc	16.3

## B. Antenna Conducted Spurious Emanations - Transmitter Crossmodulation

FM/FM TR-10 "B" Frequency Mod.

<u>Frequency</u>	<u>db "out of spec"</u>
201.0 mc	25.2
206.0 mc	38
211.0 mc	11.6
223.2 mc	17
225.4 mc	8.6
226.0 mc	28.6
229.0 mc	21.9
235.8 mc	29.7
238.2 mc	31.2
241.0 mc	5.4

FM/FM TR-10 "C" Frequency Mod.

<u>Frequency</u>	<u>db "out of spec"</u>
195.0 mc	29.3
200.4 mc	31.3
218.0 mc	13
220.5 mc	23
223.0 mc	10.2

The TR-10 is the transmitter subcomponent of the PCM/FM RF Section

Reason: 1Change Status: 6Sht. 1 of 9

REVISED \_\_\_\_\_

US 4800 2000

ENGINE VOL 53 NO D2-10889-1  
SEC X PAGE 1

**Description (continued)**

**II. The 10-20403 FM/FM Telemetry System did not meet all the specification requirements of GM 07-59-2617A. A waiver is requested for the following areas of non-compliance:**

**A. Antenna Conducted Spurious Emissions - Transmitter Keydown**

<u>FM/FM TR-10 "B" Frequency</u>		<u>FM/FM TR-10 "C" Frequency</u>	
<u>Frequency</u>	<u>db "out of spec"</u>	<u>Frequency</u>	<u>db "out of spec"</u>
206.0 mc	36.7	216.5 mc	19
214.0 mc	7	218.0 mc	23
227.0 mc	25.5	235.5 mc	18.2
229.5 mc	24	450.0 mc	9.7
245.0 mc	13	675.0 mc	25
710.0 mc	2	1.13 kmc	9
1.420 kmc	13	1.36 kmc	5
1.66 kmc	52	1.57 kmc	37
1.895 kmc	36.7	1.80 kmc	37
2.12 kmc	19.9	2.03 kmc	17
2.35 kmc	20.2	2.25 kmc	29
3.3 kmc	23.2	2.93 kmc	1

**B. Antenna Conducted Spurious Emissions - Transmitter Crossmodulation**

<u>FM/FM TR-10 "B" Frequency</u>		<u>FM/FM TR-10 "C" Frequency</u>	
<u>PCM/FM TR-10 "D" Frequency Mod.</u>		<u>PCM/FM TR-10 "D" Frequency Mod.</u>	
<u>Frequency</u>	<u>db "out of spec"</u>	<u>Frequency</u>	<u>db "out of spec"</u>
201.0 mc	38	195.5 mc	20
206.0 mc	38	201.0 mc	33.6
210.0 mc	11	217.0 mc	16
223.0 mc	17.2	221.0 mc	31.3
225.0 mc	24.6	223.0 mc	18
226.0 mc	20.6	236.5 mc	35
229.0 mc	17	680.0 mc	2.6
241.0 mc	2	689.0 mc	1.3

**C. Radiated Interference - Narrowband**

<u>Frequency</u>	<u>db "out of spec"</u>
1.66 kmc	4.8
1.894 kmc	0.8

Reasons: 

**III. The 10-20476 Staging Switch did not meet all the specification requirements of GM 07-59-2617A. A waiver is requested for the following areas of non-compliance:**

**A. Conducted Interference - .15 to 25 MC**


Current probe measurements made on the power lines in lieu of line stabilization network measurements.

Sht. 2 of 5

Description (continued)

B. Conducted Interference - 30 CFS - 150 KC


Current probe measurements in this frequency range indicate only one "out-of-specification" condition. The subject equipment was 5 db above the specification at 32.4 KC with a 20 mf capacitor shunted across the Input Power Leads external to the switch.

Reasons: 

Change Status: 

IV. The following "out-of-spec" conditions were noted on the 10-20401-1 Event Markers when subjected to the tests of GM 07-59-2617A:  
(As defined by D2-6181)

<u>Test</u>	<u>Out-of-Tolerance Conditions Noted</u>	<u>Frequency and Amount Limit Exceeded</u>
A2	Ground Wire (Black)	14 MC - .64 db
	Ground Wire (Green)	16 MC - .7 db
	Ground Wire (Yellow)	14 MC - 1.3 db
	Ground Wire (Red)	4.0 MC - .2 db
	Ground Wire (Red)	5.2 MC - 2.2 db
	Ground Wire (Red)	8.0 MC - .1 db
M1		14 MC - 4.2 db
		15 MC - 10.5 db
		25 MC - 0.8 db

Reason: 

V. The 10-20428-2 Command Destruct Receiver was not tested to the specification requirements of GM 07-59-2617A. A waiver is requested for the following areas of non-compliance:

A. Conducted Interference - 0.015 to 25 MC. The equipment was tested by employing a threshold measuring technique.

Employing this technique, a number of interference signals were recorded which were between 10 and 20 db above specification. Two interference signals were recorded which were between 20 and 30 db above specification and one was recorded which was between 30 and 40 db above specification.

B. Radiated Interference - .15 - 400 MC. Radiated measurements were also made employing the threshold technique. The data obtained during the test shows that radiated interference was above specification limits. Most interferences were between 10 and 20 db above specifications. Twelve interference signals were between 20 and 30 db above specifications, one between 30 and 40 db and one above 40 db.

Reason: 

Change status: 

Ext. 3 of 3

REVISED \_\_\_\_\_

US 4000 2000

**DOING** | VOL 53 | NO D2-10889-1  
| SEC X | PAGE 1.2

**Reasons:**

**1**

**1. Antenna Conducted Spurious Emanations - Transmitter Keydown**

- a. All interference conditions except at 201 and 223 mc were suppressed to below CM 07-59-2617A limits by the Triplexer Directional Coupler during Transmitter Cross Modulation tests.
- b. Interference signals at 201.0 and 223.0 mc appear as a result of being image frequencies.

**2. Antenna Conducted Spurious Emanations - Transmitter Crossmodulation**

**a. FM/FM "B" Frequency Modulation**

- (1) 201, 206 and 223 mc spurious signals appear as a result of being image frequencies.
- (2) All other spurious signals are within design requirements. (Requirement is for spurious signals to be 60 db below the fundamental.)

**b. FM/FM "C" Frequency Modulation**

- (1) 195, 201 and 223 mc spurious signals appear as a result of being image frequencies.
- (2) All other spurious signals are within design requirements.
- (3) The above units have operated at missile level in Seattle PET and at AMR without evidence that crossmodulation or antenna conducted spurious emanations have interfered with the operation of other instrumentation systems or reduced the accuracy or reliability of transmitted data.

**2**

**1. Antenna Conducted Spurious Emanations - Transmitter Keydown**

- a. All interference conditions except at 206.0 and 229.5 mc were suppressed to below CM 07-59-2617A limits by the Triplexer Directional Coupler during Transmitter Crossmodulation tests.
- b. Interference Signals at 206.0 and 229.5 mc appear as a result of being image frequencies.

**2. Antenna Conducted Spurious Emanations - Transmitter Crossmodulation**

**a. FM/FM "B" Frequency and PCM/FM "D" Frequency Modulation**

- (1) 201.0, 206.0 and 223.0 mc spurious signals appear as a result of being image frequencies.
- (2) All other spurious signals are within design requirements. (Requirement is for spurious signals to be 60 db below the fundamental.)

Sht. 4 of 5

REVISED

US 4880 2000

**BOEING**

VOL 53

NO D2-10889-1

SEC

X

PAGE

1.3

Reasons: (continued)

b. FM/FM "C" Frequency and PCM/FM "D" Frequency Modulation

- (1) 195.5, 201.0 and 217.0 mc spurious signals, appear as a result of being image frequencies.
- (2) All other spurious signals are within design requirements.
- (3) The above units have operated missile level in Seattle PFT and at AMR without evidence that crossmodulation or antenna conducted spurious emanations have interfered with the operation of other instrumentation systems or reduced the accuracy or reliability of transmitted data.

3 A: When the power lines were measured using the line stabilization network, the unit had one data point "out-of-specification" by 7 db. This occurred at 100 KC. It was determined that the "out-of-specification" condition was caused by the 5 uh choke in the line stabilization network tuning with a 22 uf capacitor in the input of the equipment. Subsequent tests employing the current probe technique, showed that the interference was 21 db below the specification at 150 KC and the specification was not exceeded at any frequency during this test.

B. Boeing vendor for the staging switch estimates that it will cost \$15,000 to redesign the equipment. Boeing estimates that it will cost \$10,000 to scrap the remaining units of the original configuration if it is replaced.

4 All the above "out-of-specification" conditions in Test A2 and B1 are acceptable considering the accuracy of the measuring instruments except at 14 MC and 15 MC in Test B1. It is felt that this level of radiated interference (approximately 50 uv meter indication) is not sufficient to cause degradation of the system. If any degradation of performance occurs during the MIL-I-6051 test it will be corrected at the systems level.

5 The interference conditions recorded during both the conducted and radiated interference tests were due almost entirely to destruct switching. Since this switching operation destroys the missile, it is felt that interference conditions from this switching operation will not be detrimental.

Change Status:

6 ESD Letter ESQAP-26-6-100/C. Humphrey/3938, dated 26 June 1962 authorized ESD Waiver Number ESQAP-49.

7 Authorized by ESD Letter ESQAP-31-5-97/V. Davis/3948, dated 31 May 1962.

8 ESD/STL was advised of the Cost and Time estimates to meet these requirements by Letter ESQAP-28-8-137/C. Humphrey/3938, dated 26 August 1962.

Att. 5 of 5

REVISED \_\_\_\_\_

US 4880 2000

BOEING VOL 53 NO DC-10809-1  
SEC X PAGE 1.4



Date: 7-29-63

Missile Effectivity **FTM 436**

Event Record No.:

Spec. or Doc. No.: D2-3603-3

Revision:

Date: 12-9-61

Spec. or Doc. Title: Model Specification S-133-1007C - Instrumentation  
Subsystem - Airborne - R&D WS-133A, WS-133A-M

Waiver X

Deviation \_\_\_\_\_

Page No: 239

Paragraph No: 4.4.13.1.1

**Description:**

Allow performance of the Mistram Sensitivity Test using manual sweep of the calibrate channel in lieu of automatic sweep.

**Reason:**

TX ESQA 5-7-21 directed The Boeing Company to perform Subsystem Sensitivity Tests in the manual sweep mode.

Sht. 1 of    

REVISED \_\_\_\_\_

U3 4286 2800

<b>BOEING</b>	VOL 53	NO D2-10887-1
	SEC X	PAGE 2

Date: 7-29-63

Missile Effectivity **FEM 436**

Event Record No.:

Spec. or Doc. No.: D2-3603-3

Revision:

Date: 12-9-61

Spec. or Doc. Title: Model Specification S-133-1007C - Instrumentation  
Subsystem - Airborne - R&D WS-133A, WS-133A-M

Waiver X

Deviation \_\_\_\_\_

Page No: 150

Paragraph No: 4.4.1.1

**Description:**

Allow omission of the performance of the "Power Radiated" test.

**Reason:**

Subsequent to completion of testing a defect was discovered in the teflon thermal insulating sheath on one of the telemetry antennas. The antenna was replaced and a system insertion loss and VSWR test was performed. Radiated power can be derived from previous transmitter power measurements and from the above retest data and is within tolerance. Further retest is not warranted.

Sht. 1 of    

REVISED \_\_\_\_\_

U3 4288 2000

<b>DOEING</b>	<b>VOL 53</b>	<b>NO D2-10882-1</b>
<b>SEC. X</b>	<b>PAGE</b>	<b>3</b>

Date: 7-29-63

Missile Effectivity **FTM 436**

Event Record No.:

Spec. or Doc. No.: D2-3603-3

Revision:

Date: 12-9-61

Spec. or Doc. Title: Model Specification S-133-1007C - Instrumentation  
Subsystem - Airborne - R&D WS-133A, WS-133A-MWaiver X

Deviation \_\_\_\_\_

Page No: 157

Paragraph No: 4.4.3.1.9

Paragraph Title: System Accuracy

Description:

Allow an out-of-tolerance condition during subsystem testing for the following measurements:

<u>Measurement Code</u>	<u>Reason</u>	<u>Specification Tolerance % F.S.</u>	<u>Measured Accuracy % F.S.</u>
Q037E	Note 1 ↑ ↓ Note 1	± 1.1	- 1.3
Q092E		± 1.1	- 1.3
A064T		± 1.1	- 1.2
A007E		± 1.7	+ 1.9
R015A		± 1.1	- 1.2
R063E		± 1.2	- 1.6
R049E		± 1.2	- 1.3
R050E	Note 1	± 1.2	- 1.6

Note 1: The accuracy of these channels is not sufficiently out of tolerance to appreciably degrade system performance.

Sht. 1 of

Date: 7-29-63

Missile Effectivity **FIM 436**

Event Record No.:

Spec. or Doc. No.: D2-3603-3

Revision:

Date: 12-9-61

Spec. or Doc. Title: Model Specification S-133-1007C - Instrumentation  
Subsystem - Airborne - R&D WS-133A, WS-133A-MWaiver X

Deviation \_\_\_\_\_

Page No: 143

Paragraph No: 4.2.5

Paragraph Title: Vibration Test

## Description:

- I. Allow an out of tolerance condition during Vibration tests for the following measurements:

Measure- ment Code	Reason	Spec. Tol. % F.S.	Measured Accuracy % F.S.			
			Sec. 43 X Axis	Sec. 43 Y Axis	Sec. 45 X Axis	Sec. 47 X Axis
GO37E	Note 1	± 1.1	- 1.6	- 1.6		
GO92E		± 1.1	- 1.6	- 1.4		
AO64T		± 1.1		- 1.2		
IO06E		± 1.0		+ 1.4		
EO15A		± 1.1	- 1.2	- 1.2		
EO17A	Note 1	± 1.1	+ 1.2	+ 1.2		
EO18A	Note 3	± 1.1	- 1.3	- 2.3		
EO90X	Note 3	± 1.2	- 2.3	- 1.8		
IO34E	Note 2	± 1.0	+ 3.6	+ 4.1		
AO07E	Note 1	± 1.7				+ 1.8

Note 1: The accuracy of these channels is not sufficiently out of tolerance to appreciably degrade system performance.

Note 2: Measurement IO34E is the Mistram calibrate channel AGC telemetry output. The voltage obtained is a function of the input signal level. The signal level is set to -78 dbm to make the initial voltage reading and then subsequently set up again to -78 dbm immediately prior to performance of the vibration test. The input signal level can only be set up to an accuracy of ± 3 dbm thus causing a difference in the measured input voltage and the actual input voltage to the telemetry system. This condition will not result in an appreciable degradation of flight data.

Note 3: The exhibited offset is due to excessive source capacitance in the Test Support Equipment (I.S.S.). This condition is in no way indicative of airborne instrumentation malfunction.

Sht. 1 of 2

REVISED \_\_\_\_\_

US 4300 2000

**BOEING**

VOL 53

NO D2-10009-1

SEC

X

PAGE

5

II. Allow performance of the Mistram portion of the vibration tests in a manual sweep mode.

Reason: TWX BSQA 11-6-53 directed The Boeing Company to operate in the manual sweep mode during vibration tests.

III. Allow an out-of-tolerance condition for PCM RF received signal strength during the 43X axis vibration test.

Reason: During the 43X axis vibration test, the PCM/FM and the FM/FM received signal strengths exhibited a momentary drop in level. The PCM/FM level change exceeded the specification tolerance, however, the FM/FM level change did not. Investigation of the cause of the problem revealed a broken shield on the coaxial cable connection to the ground receiving equipment. The cable was repaired and no further anomalies occurred during subsequent testing.

Sht. 2 of 2